## **DEAR FRIENDS**

## WELCOME

## RED - RH **RE-CONSTRUCTION** OF EARTHQUAKE DAMAGED **RURAL HOUSES**

#### PLATE TECTONICS



#### EARTHQUAKE ANIMATED

### Original content sourced from the BBC archive.

# PLINTH AREA 27'-2" X 22'-3" = 605sft.

# COST Rs 4.89 LAKHS

# PLINTH AREA RATE Rs. 808.26/Sq.ft.

## PROVISIONS

FOOTING DEPTH MINIMUM - 6' - 0"

• FOOTING SPREAD - 4' X 4'

• PYRAMID - OUTTER 4", INNER – 12"

#### • MIX - 1: 2: 4

#### • TOR STEEL - 12MM in Both Direction

### Number of columns - 9 Nos.

## Foundation Size For columns 4'-0" x 4'- 0" Depth of Foundation – 6'

Bars for column mesh 12mm dia. 8 nos. Both Ways. Note:

#### Mix to be used for R.C.C. 1:2:4

- Minimum Extra Length for hook
  where "d" is the diameter of
  the stirrups
- 2. Max. spacing of Stirrups near joints 1/4D up to a length of 2D, where D is the over all depth of beam /least lateral dimension of the column.



- stirrups with 135° hooks at ends required as per IS:13920-1993.





Figure 2: Two types of damage in a beam: flexure damage is preferred. Longitudinal bars resist the tension forces due to bending while vertical stirrups resist shear forces.

## Column:-

## Size 12" X 12"

TOR STEEL BARS4 nos. of 16mm dia.ELL length for column rod2' - 0"

Stirrups - 8mm dia. 9" x 9" @ 3" C/C near the joints and 6" C/C for other portion

Plinth beam12" x 12"Rod requirement4 nos. 12mm dia. rods

## **COLUMN** contd.

## Stirrups / ring rod 9" X 9" @ 3"c/c near the joints and 6" for other portions

## Height of Plinth 1' - 6"

## Height of Column up to beam level 8'- o"

Vertical bars Larger diameter steel bars that go through the full height of the column **Closed Ties** 

Smaller diameter steel bars that are made into closed loops and are placed at regular intervals along the full height of the column

> Vertical Spacing

Figure 1: Steel reinforcement in columns – closed ties at close spacing improve the performance of columns under strong earthquake shaking.

Column



Figure 2: Steel reinforcement in seismic columns – closed ties with 135° hooks are required as per Indian Ductile Detailing Code IS:13920-1993.

#### Roof beam Size $12^{"}X 16" (12" + 4")$ Cantilever beam 12" X 16" at joint and 4" at the outer end **Details of Rod – FOR BEAM** BOTTOM 3 nos. 16mm dia.

TOP2 nos. 12mm dia.

Short Piece2 nos. 16mm dia. of 6' longStirrups8mm dia. 4" @ C/C near the jointsand 6" C/C for other Portions

**Roof** beam - cantilever **Size** 12"X 16" (12" + 4") Cantilever beam 12"X 16" at joint and 4" at the outer end FOR CANTILEVER TOP 2 NOS 16mm Dia. & **2nos 12 mm** Bottom 2nos 12mm Dia.

Stirrups 8mm dia. 3" @ C/C through to end

Note: Mix to be used for R.C.C.

Minimum Extra Length for hook 10d, where "d" is the diameter of the stirrups

1:2:4

Max. spacing of Stirrups near joints 1/4D up to the length of 2D, where D is the over all depth of beam / least lateral dimension of the column

### **Roof Slab:-**

#### **Details of Rod:-**

### Main Bar: 10mm dia. @ 8" c/c both ways. Alternate Bars to be bent up

Short piece :10 mm dia. of 6' long

#### **GCI SHEET ROOFING**

- WOODEN TRUSS SHOULD BE A COMPOSITE UNIT
- JOINTS ARE IMPORTANT MORTISE & TENNION,
- TOUNGE & GROOVE, LAP JOINTS
- INTRODUCE FLAT PLATE ANGLE STRAPS WITH NUTS & BOLTS
- GCI SHEET PUNCHING THE CORRECT WAY
- REMOVING GLAZE ON SHEET BEFORE PAINT
- CORRECT USE OF LIMPET BITUMENISTIC WASHERS AND STANDARD L OR J HOOKS

#### **GOOD WORK PRACTICES**

- CLEAN SAND & AGGREGATE
- MAINTAIN WATER CEMENT RATIO
- MIX BE DONE ON CLEAN AND STRONG PLATFORM
- WASH AGGREGATES BEFORE MIX
- MAKE WOODEN BOX FOR CORRECT MEASURE
- BARS SHOULD NOT BE TAMPERED OR KINKED
- BARS SHOULD BE RUST FREE
- MAINTAIN AGGREGATE SIZE
- SECURE ALL SCAFFOLDING AND FORM WORK
- MAINTAIN SECURITY REQUIREMENTS
- MAINTAIN QUALITY & QUANTITY.

#### **MATERIAL QUANTITY - DETAIL**

Carriage	SIZE	kgs	mtr	nos / Bags
TS 16mm	16mm	675 kgs	427	35.6
TS 12mm	12mm	461 kgs	518	43.2
TS 10mm	10mm	1094 kgs	1765	147.0
TS 8mm	8mm	440 kgs	1128	94.0
		2600 kgs		
Cement				300
Bricks				6000
Sand				600
Aggregate				1200

#### Effects of completely shattered joints of concrete frame



#### Support-columns and upper deck failure,



#### Failure of <u>retaining wall</u> due to ground movement



## Shifting from foundation.











## **THANK YOU**